



PARTNERING WITH TOWNSHIPS

TOWNSHIP OFFICIALS OF ILLINOIS RISK MANAGEMENT ASSOCIATION

RISK REMINDER

What's Wrong With This Picture?



This month's risk reminder is a contest between contractors. This is a photograph of a recently visited site. The ladder is being used by a carpenter contractor to access work within the trusses and to install roof sheathing.

What OSHA regulations have been violated?
What is the proper method of abatement?

For more information, contact TOIRMA at (888) 562-7861

CLAIM REPORTING HOTLINE (844) 562-2720 | Available 24/7